

Artwork Preparation Guide for Platypus Packaging

1. File Setup

File Format:

- Submit artwork as PDF/X-4 for best compatibility with our workflow (Kodak Prinergy, Esko Plato, AGFA Apogee).
- o Ensure all links are embedded and fonts are outlined or embedded.

Color Mode:

- Use CMYK for full-color work. Convert all RGB elements prior to submission.
- Spot Colors: Clearly name all Pantone or custom spot colors (e.g., "PMS 186 C"). Avoid duplicates.

Resolution:

- Images should have a minimum resolution of 300 dpi.
- o Linework (bitmaps) should be set to 1200 dpi.

2. Document Dimensions & Bleed

- Trim Size: Match the supplied dieline/template dimensions exactly.
- Bleed: Provide at least 3 mm bleed beyond all edges of the dieline.
- Safe Zone: Keep critical content (e.g., text, logos) 3-5 mm inside the trim area to avoid being cut off.
- **Dieline Layer**: Place the dieline on a **separate layer** and ensure it is set to a non-printing color (e.g., a magenta stroke).

3. Color & Ink Management

- White Ink: Clearly label any artwork requiring white ink, particularly for printing on transparent or kraft materials.
- Overprinting: Indicate which elements require overprint settings (e.g., for spot varnishes or white ink knockouts).
- Rich Black: Use C=60%, M=40%, Y=40%, K=100% for solid black areas. Avoid 100% black-only for large coverage.
- Varnishes/Emboss/Deboss:
 - Use a spot color for special effects like varnish, embossing, debossing, or foiling.
 - Label each spot color clearly (e.g., "Spot_Varnish").

4. Fonts & Text

- Text Size: Minimum font size for legibility: 6 pt for positive text, 8 pt for reversed-out text.
- Font Outlining: Convert all fonts to outlines if not embedding them.
- Text Lavers: Keep text on a separate laver for prepress clarity.

5. Barcodes & Variable Data

- Barcodes:
 - o Ensure barcodes are vector-based with a minimum resolution of 300 dpi.
 - o Maintain a clear margin around the barcode (minimum **3 mm** guiet zone).
- Variable Data:
 - Submit as a separate CSV or Excel file.
 - o Reference variable fields clearly in your artwork document.

6. Layers & Naming

- Clearly separate artwork into logical layers:
 - Artwork (CMYK/Spot Color)
 - o Dieline
 - Varnish/Emboss/Deboss
 - White Ink
 - Guidelines (non-printing)

7. Proofing

- Soft Proofs: Use a color-calibrated monitor when reviewing PDF proofs.
- Hard Proofs: Request a hard proof if accurate color or dieline alignment is critical.

8. File Submission

- Name files logically:
 - [JobName] [Version] DATE.pdf
 - Example: Platypus Box Lid V1 120624.pdf
- Submit final files via a file transfer system.
- Ensure all linked files, dielines, and special requirements are included.

9. Preflight Checklist

Before submitting files:

- Trim size and bleed match the dieline
- ☑ Images are 300 dpi (or 1200 dpi for bitmap)
- CMYK and spot colors are correct
- ▼ Fonts are outlined/embedded
- ☑ No RGB, transparencies, or low-resolution images
- White ink, varnish, or special effects are clearly labeled

This guide ensures compatibility with our Kodak Prinergy, Esko Plato, and AGFA Apogee workflows and streamlines your packaging production process.

For questions, contact our Prepress team at [prepress@platys.com.au].